wöhner

NH – Fuse-links
Time current characteristic curves

gL/gG
Size 000
690 V AC



Pre-arcing Time (s)

RMS value of the perspective current (A) +/- 10%

wöhner

NH – Fuse-links
Time current characteristic curves

gL/gG
Size 00
690 V AC

Pre-arcing Time (s)



RMS value of the perspective current (A) +/- 10%

wöhner

NH – Fuse-links
Time current characteristic curves

gL/gG
Size 1
690 V AC



Pre-arcing Time (s)

RMS value of the perspective current (A) +/- 10%

wöhner

NH – Fuse-links
Time current characteristic curves

gL/gG
Size 2
690 V AC



wöhner

NH – Fuse-links
Time current characteristic curves

gL/gG
Size 3
690 V AC



wöhner

NH – Fuse-links
Cut-off Current characteristic

gL/gG
Size 000
690 V AC

Max. peak let-thru current Ic (A)



50 Hz RMS value of the perspective current Ip (A)

gL/gG
Size 00
690 V AC

Max. peak let-thru current Ic (A)



50 Hz RMS value of the perspective current Ip (A)

wöhner

NH – Fuse-links
Cut-off Current characteristic

gL/gG
Size 1
690 V AC

Max. peak let-thru current Ic (A)



50 Hz RMS value of the perspective current Ip (A)

wöhner

NH – Fuse-links
Cut-off Current characteristic

gL/gG
Size 2
690 V AC



Max. peak let-thru current Ic (A)

50 Hz RMS value of the perspective current Ip (A)

gL/gG
Size 3
690 V AC



Max. peak let-thru current Ic (A)

50 Hz RMS value of the perspective current Ip (A)