

Montageanleitung

94 227

Typ	Gerätebefestigung mit Schraube	Einpreßbuchse Durchmesser x Länge	Lochbild Nr.	Einschraubtiefe Befestigungsschraube min. - max.
Wöhner				
03 709				
03 831				
03 824	3 x M8	∅10 x 13	12 + 13 + 22	15 - 18
03 861				
03 711	4 x M8	∅10 x 13	8 + 11	15 - 18
03 833			18 + 19	
Siemens				
3NP4290	2 x M6	∅8,5 x 11	16 + 17	11 - 13
3NP5230	4 x M8	∅10 x 13	9 + 10	15 - 18
3NP5330			20 + 24	
* 3NP5430	4 x M8	∅10 x 13	30 + 31 32 + 33	15 - 18
3KE4230	4 x M6	∅8,5 x 11	1 + 4	11 - 13
3KE4330			27 + 28	
3KE4430	4 x M6	∅8,5 x 11	1 + 5 27 + 29	11 - 13
3KA5330	4 x M4	∅6 x 8	2 + 3 21 + 23	10 - 13
3KA5530				
3KA5730	4 x M6	∅8,5 x 11	6 + 7	11 - 13
3KA5830			25 + 26	
ABB				
OETL200K3	4 x M6	∅8,5 x 11	34+35+36+37	11 - 13
Sonderausführung OETL400D1	4 x M6	∅8,5 x 11	1+5+27+29	11 - 13
Sonderausführung OETL630K3	4 x M6	∅8,5 x 11	1+38+27+39	11 - 13

* Sonderausführung auf Anfrage